



2495.000008.1

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
JEFFREY ESTRELLA ET AL.)
Appln. No.: 10/775,682)
Filed: February 10, 2004)
For: BEZEL FOR FIBER OPTIC)
COMPONENTS)
U.S. Patent No.: 7,036,994 B2)
Issued: May 2, 2006)
Examiner: H.M. Hyeon
Art Unit: 2839
September 20, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Certificate
SEP 25 2006
of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

09/21/2006 SDENB081 00000129 7036994

01 FC:1811


100.00 0P

SEP 26 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

A handwritten signature in black ink, appearing to read 'Frank A. DeLucia', is written over a horizontal line.

Frank A. DeLucia
Attorney for Patentees
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 590540v1

SEP 26 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,036,994 B2

DATED : May 2, 2006

INVENTOR(S) : JEFFREY ESTRELLA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 15, "Often times" should read --Oftentimes--;
Line 48, "to" should be deleted; and
Line 65, "couple" should read --coupler--.

COLUMN 2:

Line 15, "DRAWING" should read --DRAWINGS--.

COLUMN 3:

Line 26, "therein." should read
--therein.

It will be appreciated by one of skill in the art, that the bezel cover in the cover in the closed position is preferably flush with a vertical access panel surface of an optical connection box. Thus, the housing of the bezel is connected with the optical module at a downward angle, shown as angle A with a horizontal reference in Figure 2. Positioning the bezel at a downward angle relative to a vertical access panel helps to avoid any potential eye injury to a technician working with the coupler within the bezel. Accordingly, if the bezel housing was instead mounted substantially

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,036,994 B2

No. of add'l. copies
@ 30¢ per page



SEP 26 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,036,994 B2

DATED : May 2, 2006

INVENTOR(S) : JEFFREY ESTRELLA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

perpendicular to the access panel, a technician might accidentally look directly into the optical coupler, and thus the light path, within the bezel housing potentially damaging his vision. By mounting the bezel housing at a downward angle, the direction of light emanating from the optical coupler within the bezel housing is downward away from the eye level of a technician and toward the ground.--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,036,994 B2

No. of add'l. copies
@ 30¢ per page



SEP 26 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,036,994 B2

DATED : May 2, 2006

INVENTOR(S) : JEFFREY ESTRELLA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 15, "Often times" should read --Oftentimes--;

Line 48, "to" should be deleted; and

Line 65, "couple" should read --coupler--.

COLUMN 2:

Line 15, "DRAWING" should read --DRAWINGS--.

COLUMN 3:

Line 26, "therein." should read
--therein.

It will be appreciated by one of skill in the art, that the bezel cover in the cover in the closed position is preferably flush with a vertical access panel surface of an optical connection box. Thus, the housing of the bezel is connected with the optical module at a downward angle, shown as angle A with a horizontal reference in Figure 2. Positioning the bezel at a downward angle relative to a vertical access panel helps to avoid any potential eye injury to a technician working with the coupler within the bezel. Accordingly, if the bezel housing was instead mounted substantially

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,036,994 B2

No. of add'l. copies
@ 30¢ per page



SEP 26 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,036,994 B2

DATED : May 2, 2006

INVENTOR(S) : JEFFREY ESTRELLA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

perpendicular to the access panel, a technician might accidentally look directly into the optical coupler, and thus the light path, within the bezel housing potentially damaging his vision. By mounting the bezel housing at a downward angle, the direction of light emanating from the optical coupler within the bezel housing is downward away from the eye level of a technician and toward the ground.--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,036,994 B2

No. of add'l. copies
@ 30¢ per page



SEP 26 2006